本資料の無断転用、複写を禁じます

Tornado Damage in Midwest U.S

December 11, 2021

Cover Image: Homes and Buildings Destroyed by Tornadoes | Mayfield, Kentucky, U.S. | December 11, 2021 | Maxar WorldView-3 Satellite Image Mayfield, Kentucky December 11, 2021 WorldView-3 Monette, Arkansas December 11, 2021 GeoEye-1



Monette Manor nursing home

Edwardsville, Illinois December 11, 2021 High off-nadir WorldView-1



Aftermath of Tornado Damage | Kentucky, Arkansas and Illinois | December 11, 2021 | Maxar Satellite Images

Destroyed Mayfield candle factory

Heavily damaged Amazon distribution center warehouse

3.00



Mayfield Candle Factory | Mayfield, Kentucky | January 28, 2017 | Maxar WorldView-2 Satellite Images



Aftermath of Tornado Damage at Mayfield Candle Factory | Mayfield Kentucky | December 11, 2021 | Maxar WorldView-3 Satellite Images



Significant roof damage

Pil Sta



Heavily damaged county courthouse building

Sec. 1

24

6

Aftermath of Tornado Damage | Mayfield, Kentucky | December 11, 2021 | Maxar WorldView-3 Satellite Images

Before tornado

5:25:

Maarina

11141

0

\$

....

After tornado

Aftermath of Tornado Damage | Mayfield, Kentucky | December 11, 2021 | Maxar WorldView-3 Satellite Images



Before tornado September 24, 2021





Aftermath of Tornado Damage | Edwardsville, Illinois | December 11, 2021 | Maxar WorldView-3 Satellite Images